



Loop lead pairs	1-2	3	4-5	6-8	9-12
Conduit size (MIN)	1 ′′	11/4"	11/2"	2"	3′′

TABLE A




SPLICE DETAIL





LEAD - IN SAWCUTS AND CONDUIT PLACEMENT DETAIL

DETAIL A

INDUCTION LOOP DETAILS








TYPE 1 TYPE 2

TYPICAL CORNER SAWCUT
LOOP SAWCUT DETAILS

LOOP WINDING DETAILS



- 1) Sealant
- 2 Twisted polypropylene rope (Sized for snug fit)
- 3 Loop wire number varies (See Loop Winding Details)
- (4) Lead-in wires: One pair for each loop served, three pairs maximum per sawcut (See installation notes)
- 5 Extend sawcut sufficient length to provide full sawcut depth around corners

LOOP INSTALLATION NOTES

- 1. Install junction box and lead-in conduit.
- 2. Saw loop slots and lead-in slots.
- 3. Lay out loop wire begining at junction box, allowing 5' minimum slack.
- 4. Install wire in loop slot. See Loop Winding Detail.
- 5. Return to junction box and identify leads with plan detector number and "S" for start and "F" for finish.
- Twist each pair of lead-in wires two turns per foot from loop to junction box and install in lead-in slot and conduit. Reverse direction of twist for each successive pair installed.
- Construct supplemental splice containing any series or parallel loop connections required in plans. Supplemental splices are subject to the same requirements shown for the loop lead and shielded cable splice.
- 8. Splice loop leads or supplemental splice leads to shielded cable as noted.
- 9. Complete installation and test loop circuits or combination loop circuits.
- 10. Front of loop should be measured from back of stop bar, or back of crosswalk where no stop bar is installed.
- 11. Seal ends of conduit.

INDUCTION LOOP DETAILS